

supplementary

Honda CBR 1000 2004 -07



1) Ignition coils


Disconnect natural Sumitomo connector (6way) placed on right side near cylinder head - pic.1
Insert QS wiring harness - see picture below - pic.2

2) Ground connection

Connect black wire of QS wiring harness to negative terminal of battery (or to frame of motorcycle)

3) QS sensor

Connect QS sensor to QS wiring harness - black 2 pin connector.



Pic.1 - location of 6way connector from Ignition coils

